AT-D578UV
Firmware & CPS Change Log

The updates in this change log only apply to the AnyTone® AT-D578UV Radio. Before doing any firmware updates, please check your model by going to the Device INFO Menu, located in Menu->Settings, and selecting Device Info. Under Model it will say 578UV. If your radio says 578UVII, please download the firmware package that shows firmware that starts with a 2.

*** USB Drivers – For Windows 10 and Windows 11 systems, you do not need to install any drivers. Connect the radio with the programming cable, turn on the radio, and once it is fully booted up, Windows will detect and install the correct drivers. If you are still on the Date and Time screen, it will not detect the radio. You must be on the main radio screen.

For Windows 7/8 Systems, please install the USB driver available at:https://w9jam.com/anytone-firmware-cps-guides/

D578UV --- Please use the firmware D578UV_V1.xx for updating the radio.

D578UVII --- Please use the firmware D578UVII_V2.xx for updating the radio.

Firmware V1.22 | 2026-11-07

Changes

1. Fixed an issue in which the D578UV cooling fan did not operate as expected. Due to the modification of the detection logic for fan activation, some radios may experience premature fan activation, which cannot be rectified. It is recommended to set the fan activation to only occur during transmission.
2. Improved digital APRS operation on AT-version radios.
3. Separated out the TX and RX Color Code settings for each channel.
4. Added eight fixed-position entries to the APRS page for Fixed Beacon use.
5. Added Maidenhead locator display to GPS information.
6. Changed the GPS icon to a green satellite icon. (Designed by IK8JHL.)
7. Added Master Radio ID functionality, matching the D878UV.
8. Improved the popping sound that could occur at the start of transmission or while listening to a QSO.
9. **CPS > Optional Setting > Other > Sub Spk in TX:** Setting this option to Off prevents received APRS packet audio from being transmitted.
10. Added the ANA SQL key function for quick adjustment of the analog squelch level. The function is available on both the radio and the BT01 microphone; the BT01 also requires a compatible firmware upgrade.
11. Fixed an issue in which an incoming APRS packet could interrupt APRS SMS composition and return the radio to the main screen.
12. **CPS > Tool > JSON Data Import/Export:** Added the ability to export a JSON file containing Optional Settings and other radio settings. Importing the JSON file preserves the maximum number of compatible settings. This tool is compatible with the D878UV, D878UVII, D578UV, D168UV, and D890UV.
13. Fixed an issue where when using an analog channel with digital APRS TX, the radio device transmits using a random DMR ID instead of the DMR ID set in the channel.

Firmware	CPS	Icon	SCT 3258	BT Version	APRS Version	BT01 Firmware
V1.22c	V1.22	-	V2.01.07 BF	10043 or 19043	V2.00 or V1.06	V1.03c

Firmware V1.21 | 2024-6-19

Changes

1. Improved an issue in which the BT01 could become stuck at “Roaming... Please Wait!” while operating with the radio.
2. Fixed an issue in which the “Zone Hide” function did not work correctly on the BT01 Bluetooth microphone.

Firmware	CPS	Icon	SCT 3258	BT Version	APRS Version	BT01 Firmware
V1.21	V1.21	-	V2.01.07 BF	10043 or 19043	-	V1.02

Firmware V1.20 | 2024-1-31

Changes

1. Improved an issue in which the radio load 1.19.2 firmware, the green LED keeps on when power on the radio.

Firmware	CPS	Icon	SCT 3258	BT Version	APRS Version	BT01 Firmware
V1.20	V1.20	-	V2.01.07 BF	10043 or 19043	-	V1.01

Firmware V1.19.2 | 2023-9-25

Changes

1. Improve the scan speed, ignore some burst signal.
2. Modify the SMS to support the Text Capture on BM.
3. Modify the CPS to prohibit the CPS read the AES / ARC4 encryption from the radio, and prohibit the CPS read the AES / ARC4 encryption from the codeplug. We suggest you export the AES / ARC4 encryption codes from the old CPS and save it on your PC, in case you need to create the codeplug, you can import the encryption codes.
4. Fixed an issue in which sometimes D578UV stuck when using the BT01 through Bluetooth wireless connection.
5. Fixed an issue in which D578UV has a frequency shift when power on the D578UV with repeater function default ON.
6. Modify the firmware to make the AES encryption have a variable Vector (IV) instead of fixed “12345678”.

Firmware	CPS	Icon	SCT 3258	BT Version	APRS Version	BT01 Firmware
V1.19.2	V1.19	-	V2.01.07 BF	10043 or 19043	-	V1.01

Firmware V1.18 | 2023-4-21

Changes

1. CPS > Digital > ARC4 encryption, add the ARC4 encryption which is compatible with Motorola.

2. CPS > Optional Setting > Digital > Voice Header Repetitions, allows you to set the voice header transmit times to sync the receive radio, it will improve the communication success rate with RX radio.

3. CPS > Optional Setting > Digital > TX preamble to define the preamble time of the data transfer function (not needed for audio calls), and improve synchronization

4. SMS confirmation mode improvements with better compatibility with other devices

5. Call Alert fully compliant with ETSI recommendation

6. Fixed an issue in which when BT01 is connected, the radio freezes when sending APRS.

7. Fixed an issue in which BT Mic Gain setting in CPS does not load into BT01 when programming the BT01 microphone.

8. Fixed an issue in which BT01 custom Bluetooth name is incorrect after rebooting the BT01 microphone.

9. Fixed an issue in which D578UV does a reset when the radio loses power while scanning air-band channels, which caused the D578UV has to reload the codeplug.

10. Fixed an issue in which D578UV does not display the active air channel information during scanning, it still shows the initial air channel when start the scan.

Firmware	CPS	Icon	SCT 3258	BT Version	APRS Version	BT01 Firmware
V1.18	V1.18	-	V2.01.07 BF	10043 or 19043	-	V1.01

Firmware V1.17 | 2022-12-8

Changes

1. Channel > Analog > 5Tone ID, make the decode standard in current channel to be same as the 5Tone ID encode standard.
2. Upgrade the firmware to work with BT01 Bluetooth microphone.

Firmware	CPS	Icon	SCT 3258	BT Version	APRS Version	BT01 Firmware
V1.17	V1.17	-	V2.01.07 BF	10043	-	-

Firmware V1.16 | 2022-7-6

Changes

1. Set the sub band default OFF when GPS roaming is turned On, to avoid the issue that sub band VFO channel jumps to random channel.

2. Fixed an issue in which exports to .dcf file does not work with Contact Manager V270.

3. Improved an issue in which radio cracks when SFR repeater is running, requires an upgrade on the SCT to resolve this issue.

4. In CPS > Scan list > Digi Group Hold Time, Digi Pri hold time, add the hold time setting when receiving signal at digital channel during scanning.

Firmware	CPS	Icon	SCT 3258	BT Version	APRS Version	BT01 Firmware
V1.16	V1.16	-	V2.01.07 BF Update file included to upgrade from SCT BA to BF	10036	-	-

---

Firmware V1.15 | 2021-11-30

Changes

1. Allow to select TG and RX group list for the new channel created in the radio menu.
2. Improve the Single Frequency Repeater unstable problem.
3. CPS > APRS > Analog, add 8 groups analog TX frequency. In CPS > Channel > Analog APRS Report Freq, allows you to select a TX frequency to transmit the analog APRS.
4. CPS > Common Setting > Channel > DMR Mode, add “DCDM TS Split” mode. In this mode, the radio receives the selected slot in the channel, but in transmission it will use the other slot. This configuration is only in use when the radio talk through a D578UV in repeater mode with a fixed slot.
5. CPS > Optional Setting > Auto repeater, add 3 new functions. These 3 functions are only working when the Repeater function is set ON.

   Rep CC Limit: Repeater is not working when the color code does not match.

   Rep Slot Path A: Repeater will receive at a fixed slot on channel A and transmit in the other slot on channel B.
   Rep Slot Path B: Repeater will receive at fixed slot on channel B and transmit in the other slot on channel A.
6. CPS > Common Setting > GPS Roaming, allows users to set a list of GPS locations, when GPS positioning is within the preset radiation radius of coordinates, the radio will switch to the corresponding zone. 1)Common Setting > Optional Setting > GPS/Ranging > GPS set ON.
   2) Common Setting > Optional Setting > GPS/Ranging > GPS Roaming set ON.
   3) Common Setting > Optional Setting > GPS/Ranging > Distance unit,select Meter or Feet for the radius.
   4) Common Setting > GPS Roaming, complete the setting, maximum 16 coordinates can be set with a matched zone.
5. CPS > Common Setting > Zone > Zone hide, add Zone Hide function in the Zone menu, it allows the user to hide some zone when they don’t need it on display. Since the Zone Hide is a newly inserted item, it may be checked automatically when opening an existing codeplug. CPS > Tool > Zone Hide Operation, allows you to check or uncheck all Zone Hide.
6. Add APRS SMS function in the radio menu, allowing the radio to receive and transmit APRS messages.
7. CPS > Common Setting > Channel > Send Talker Alias, make the Talker Alias to be a private setting for each channel, instead of a public setting for all channels.
8. CPS > Tool > APRS information Manager, allows the CPS to read the received APRS message from radio and export.
9. Add “Draft” in the Messages menu, unsuccessful SMS is saved in Drafts and can be resent.
10. Add timezone GMT+5:30(India), GMT+5:45 (Nepal), GMT+4:30(Afganistan), GMT+3:30(Iran) GMT-3:30 (Newfoundland, Canada), GMT+8:30 (Eucla)
11. Change the APRS message to be a lower priority than menu, the radio will not be kicked out of the radio menu when receiving the APRS message.
12. Correct the analog APRS sending inaccurate altitude (height) issues.
13. Correct the corrupted alert tone issue.
14. Make the TOT valid for the cross-band repeater function.

Firmware	CPS	Icon	SCT 3258	BT Version	APRS Version	BT01 Firmware
V1.15	V1.15	-	V2.01.07 BA (same, no update required)	10036	-	-

---

Firmware V1.14 | 2021-05-31

Changes

1. CPS > Optional setting > Display > Date Display Format, allows the user to set the date format on display.
2. CPS > Optional setting > Display > Display Channel type, allows the user turn off the channel type on display
3. CPS > Optional setting > Display > Display time slot, allows the user turn off the time slot on display
4. CPS > Optional setting > Display > Display color code, allows the user turn off the color code on display

5. CPS > Optional setting > Alert Tone, add Ana idle channel tone, the digital channel and analog channel have separated idle channel tone setting.
6. CPS > Channel > Auto scan, tick on the box will allow the radio start scan automatically.
7. CPS > Optional setting > Volume/Audio, separate mic gain setting for digital channel and analog channel
8. CPS > APRS > Ana AprsTX, allows to set wide band or narrow band for analog APRS transmit.
9. Add the alert tone setting in the radio menu.
10. CPS > Analog > 2Tone Setting > Auto Reset Time changes to maximum 250S. If you set Auto Reset Time to 25s, it keeps the squelch on the carrier until there is 25 seconds of silence, then it switches back to waiting for tones. If there is a transmission before the end of that 25 secs, the timer restarts. It is useful for the 2Tone Paging System.
11. CPS > Analog > 5Tone Setting > Auto Reset Time changes to maximum 250S
12. CPS > Analog > DTMF > Auto Reset Time changes to maximum 250S

Firmware	CPS	Icon	SCT 3258	BT Version	APRS Version	BT01 Firmware
V1.14	V1.14	-	V2.01.07 BA (same, no update required)	10036 (last version is 10033, you can stay at 10033 if you don't need to use Android APP).	-	-

---

Firmware V1.13 | 2021-04-13

Changes

1. Fixed an issue in which the talker alias transmit does not match to selected Radio ID when there are several Radio ID set in radio.
2. CPS > Digital > Digital Contact list upgrade from 200K to 500K
3. Fixed an issue in which "when sending APRS Beacon it transmits three times instead of once, when transmittingting APRS Beacon with PTT it transmits it twice instead of once"
4. Fixed an issue in which B band can not decode APRS.
5. Fixed an issue in which "If you activate the function Repeater FM to FM, the audio does not pass through (when the MAIN band is on A the audio works)"
6. Fixed an issue in which "A click-bump after PTT is pushed for transmitting voice is sent before the audio modulation from mic is transmitted"
7. CPS > Tool > Options, add Analog APRS RX option, allows users to choose whether the Analog aprs RX setting is valid according to the radio version.

Firmware	CPS	Icon	SCT 3258	BT Version	APRS Version	BT01 Firmware
V1.13	-	-	-	-	-	-

Firmware V1.12 | 2021-02-06

Changes

1. CPS > APRS > AprsDisTime, allows setting the APRS display time on the screen.
2. CPS > APRS > AprsAltData, allows setting the APRS altitude to fixed beacon use.
3. CPS > Optional Setting > Key function, rename the key function " FM radio" to "AM/FM"
4. CPS > Public > APRS > Analog > Digipeater Path, allows input more digipeater paths. (for all D578UV models)
5. CPS > Optional Setting > GPS Ranging > Time Zone change from GMT to UTC
6. Change the channel type to indicate icon to cyan color when the mixed channel receives analog signal.

7. CPS > Optional Setting > Alert Tone > Key Tone, change to turn off the key tone only. Other beep tones are keeping on.

8. CPS > Analog > 5Tone > 5Tone decode units, allows to filter the income 5Tone ID. For example, if the setting is 109, the radio will receive all the calls 5Tone ID starts with 109.

Firmware	CPS	Icon	SCT 3258	BT Version	APRS Version	BT01 Firmware
V1.12	V1.12	-	V2.01.07 BA (same, no update required)	10036 (last version is 10033, you can stay at 10033 if you don't need to use Android APP).	-	-

---

Firmware V1.11 | 2020-09-18

Changes

1. Improve the firmware issue that cross band repeater Analog –> Digital or Analog > Analog does not transmit the audio.

2. Improve the firmware issue that manual dial TG TX in simplex channel does not show busy when the radio is receiving.

3.Simplex Channel for a Hotspot TX Permit = Channel free or Different CC

4. Added Manual dial a TG

5. When you PTT when the radio is RXing someone the Radio does not show Busy, it just lets you TX into the Hotspot. It should see that it is in use and show Busy

6. Improve the CPS issue that channel setting TX permit set to Same Color Code, reopen the channel setting will show Always.

Firmware	CPS	Icon	SCT 3258	BT Version	APRS Version	BT01 Firmware
V1.11	V1.11	-	V2.01.07 BA (same, no update required)	10036 (last version is 10033, you can stay at 10033 if you don't need to use Android APP).	-	-

---

Firmware V1.10N | 2020-09-08

Changes

1. Improved an issue in which radio will grab a TG when the repeater is in Call Hold Off time.

2. Improved an issue in which “GPS information does not display with using a programmed “GPS info” key when only analog channels are in use”.

3. Improved an issue in which “By receiving Dmr in Simplex and Double Slot mode, several times the demodulated audio of the first word is missing”.

4. CPS > Channel > Analog, R5toneBot, R5tone Eot, allows to set different 5Tone PTT ID for each channel.

5. Fixed an issue in which “By composing a 5 tone using Manual Dial (Book, Manual Dial, typing Input ID and pressing PTT, the "stop code" defined in 5 tone setting is not considered as silence (stop code and stop time) but as a tone”.

6. When 5Tone > Beep Tone & Respond are enabled, the radio will respond with itself ID.

7. CPS > Key function, add APRS sent to the key function. The radio will transmit the APRS information (longitude, latitude,etc.) to the receiver when the user presses the “APRS send” key.

8. Improved an issue in which a digital monitor displays the wrong time slot.

9. Improved an issue in which “Keeping the sub band enabled, reception on the Main band is often lost or is very delayed”.

10. Improved an issue in which “After decoding a 5-tone call in repeater mode, the 5-tone response is sent only after the repeater has dropped out”.

11. Improved an issue in which “By configuring the 5 tones selective call for different call types, starting from when the RF carrier is on pushing PTT, the timing of the beginning of 5 tones sequence does not correspond to the summation of pauses configured in 5 tone setting windows in the CPS. Unexpected delay is also present using DTMF and 2 tone”

12. CPS > Digital > Talk Groups, allows the entry of talk group numbers maximum 16777215.

13. When viewing Last Heard contact, Options selection is not available, like it is on the 878. Add the Options selection to D578.

Firmware	CPS	Icon	SCT 3258	BT Version	APRS Version	BT01 Firmware
V1.10N	V1.10N	-	V2.01.07 BA (same, no update required)	10036 (last version is 10033, you can stay at 10033 if you don’t need to use Android APP).	-	-

---

Firmware V1.09N | 2020-6-16

Changes

1. CPS > Optional Setting > Display > Zone Name Colour, allows to set the display color of zone name.

2. CPS > Optional Setting > Other > Auto shut down type, allows setting the auto power off count time to be affect by call or not.

3. Improved an issue in which radio has Click sound during scan.

4. CPS > Channel > DataACK Disable, allows to disable the radio response to repeater data service requests. It helps to improve the radio freeze issue.

5. Press Menu key on radio to stay at the channel with signal permanently when it finds a signal during scanning. The radio is unable to switch to that channel if the channel does not belong to a zone.

6. Change the default date time to the year 2020.

7. Separate the TOT prompt tone and the beep tone.

Firmware	CPS	Icon	SCT 3258	BT Version	APRS Version	BT01 Firmware
V1.09N	V1.09	-	V2.01.07 BA (same, no update required)	10036 (last version is 10033, you can stay at 10033 if you don’t need to use Android APP).	-	-

---

Firmware V1.08 | 2020-5-18

Changes

1. Allows the radio to send APRS in the hold time.

2. Improved an issue in which radio gets stuck when both APRS and Roaming are ON.
3. Improved an issue in which SMS format is incorrect when CPS reads the data from radio.
4. Set SMS default to M-SMS.
5. Allows to set multiple signal paths for APRS and separate them by comma.
6. Improved an issue in which DMR mode is incorrect when CPS reads the data from radio.
7. Release the APP for Android mobile phone use.

Firmware	CPS	Icon	SCT 3258	BT Version	APRS Version	BT01 Firmware
V1.08	V1.08	-	V2.01.07 BA（same, no update required）	10036 (last version is 10033, you can stay at 10033 if you don't need to use Android APP).	-	-

---

Firmware V1.07R | 2020-4-30

Changes

1. Improved an issue in which the radio sent APRS at the wrong time slot.
2. Improved an issue in which radio transmits at the wrong time slot randomly.
3. Improved an issue in which CPS does not load the QX FW Update program as full screen.
4. Add notice in CPS for Import Operation.

Firmware	CPS	Icon	SCT 3258	BT Version	APRS Version	BT01 Firmware
V1.07R	V1.07R	-	V2.01.07 BA（same, no update required）	10033 （same, no update required）	-	-

---

Firmware V1.07 | 2020-4-25

Changes

1. Fixed an issue in which analog RX with CTCSS/DCS is intermittent.
2. In CPS-Optional Setting - STE, add STE time setting, it is for analog squelch tail eliminator.
3. Fixed an issue in which export has a problem when checking on the “Exclude Channel From Roaming” and “DMR MODE”.
4. Add CTCSS/DCS Scan
5. Fixed an issue in which Call Tone /Call Reset Tone/Channel Idle Tone have noise.
6. Fixed an issue in which 220MHz analog repeater channels no RX audio.
7. Change the APRS RX display to callsign instead of channel name display.
8. Add the“channel name/frequency display switch” to the key function.
9. Add SFE operations to the radio menu.
10. Improve the TX cut off issue
11. Improved an issue in which no RX when receiving a signal from analog repeater with CTCSS decode signaling（need verification from tester）
12. Change the maximum Bluetooth dormant time to 4minutes, and add OFF option to the BT dormant time.
13. Improved an issue in which radio transmit to wrong TG
14. Rename the key function “Program Scan” to “VFO Scan” to avoid misunderstanding.

15. Fixed an issue in which auto APRS and auto Roaming don't work when the group call/private call hold time is set to Infinite.
16. Improved an issue in which radio stuck/rebooted when both auto roaming function and auto APRS function were on.

Import Notice on the Export and Import function.

The new CPS 1.07 has some increased items, which cause it is not compatible with the old version CPS. We recommend doing the below operation.

1) Use the CPS 1.06 to save the codeplug to.rdt file.
2) Use the CPS 1.07 to open the.rdt file.
3) Use the CPS 1.07 to export the files.
4) Use the CPS 1.07 to import the files.

The.rdt file is always compatible with old versions of CPS.

The import/export is not compatible with the old version CPS, import/export should be done in the same CPS.

Firmware	CPS	Icon	SCT 3258	BT Version	APRS Version	BT01 Firmware
V1.07	V1.07	-	V2.01.07 BA (same, no update required)	10033 (same, no update required)	-	-

---

Firmware V1.06 | 2020-1-18

Changes

Improved the RX stuck up issue

SCT3258 version is the same, no update required on the SCT3258.

AnyTone is on CNY holiday Jan19-Feb 2, any comments please send to the AnyTone dealers, we will collect and improve after the CNY holiday, thanks.

Firmware	CPS	Icon	SCT 3258	BT Version	APRS Version	BT01 Firmware
V1.06	V1.06n	-	2.01.07BA	10033	-	-

Firmware V1.05 | 2019-12-25

Changes

1. Fixed an issue in which Beep sound does not work when the repeater is out of range.
2. Fixed an issue in which the up/down key function on the microphone is reversed in VFO mode.
3. Revise the beep tone time setting.
4. Add off option for Talker Alias and SMS
5. Fixed an issue in which APRS-Auto TX interval setting in CPS does not match the radio menu.
6. Add GPS On/Off in the key function
7. Add BT On/Off in the key function
8. During scanning, the removed channels from channel list will revert back after switching zone.
9. **CPS > Channel > Digital > multi-key, add encryption (MKE) function. (Note:** When use the MKE function, make sure turn off the sub channel, otherwise the RX will be affected)
10. CPS > Channel > Digital > random key, allows the radio transmit the random key encryption.
11. Fixed an issue in which when roaming is ON, the POP-up screen shows OFF.
12. Fixed an issue in which in APRS section, Slot2 selection is radio broadcast for Slot1 and vice versa.
13. Fixed an issue in which the car audio stops when starting the roaming function.
14. Fixed an issue in which the car audio stops when APRS is transmitting.

15. Fixed an issue in which the fan remains on after the temperature has returned “low”
16. Fixed an issue in which the power is low in single frequency repeater function.
17. Optional Setting > Display > Standby Char Color, allows to set different colors.
18. Fixed an issue in which D578UV set encryption have Chinese prompt message
19. Modify the Mode 0018 to allow receive on full frequency band.
20. CPS-Optional Setting - Other- Weather Alert and Weather channels, matches to the radio menu.
21. CPS-Public-Channel-SMS Confirmation, update the help information
22. CPS-Public-Channel-Call Confirmation, update the help information

Firmware	CPS	Icon	SCT 3258	BT Version	APRS Version	BT01 Firmware
V1.05	V1.05	-	2.01.07BA	10033	-	-

Firmware V1.03 | 2019-10-31

Changes

1. In CPS > Optional Setting > Key function > Short key push, long key push, allows the channel selector programmable for different functions.
2. Resolved the analog APRS can not reach aprs.fi issue.
3. Resolved the issue that the GPS info does not show on screen when press the programmed “GPS info” key in an analog channel.
4. Resolved the issue that digital - digital cross band repeater function will cause the radio to be stuck.
5. Improved the MMDVM RX signal chopping issue.
6. Resolved the issue that B band digital channel no audio when A band analog channel in scanning mode.
7. Resolved the green indicates light flash issue during the scan.
8. Improved the Weather alarm function.
9. Resolved the issue that the digital-analog cross band repeater function does not work when the digital monitor is ON.
10. In CPS > Optional Setting > Key function, new key function “repeater” which allows to assign a key to turn ON/OFF the cross band repeater function.
11. Resolved the issue that # key will not save the contact and color code when the digital monitor is ON.
12. In the radio menu - setting - radio set - Fan open, add “both” option to allow the fan open in both conditions.
13. When cross band repeater function is ON, the TX prohibit function will be invalid.
14. Resolved the cross band repeater sometimes does not TX.
15. Improving the MMDVM RX signal will cause radio stuck issues.
16. Resolved the band does not correctly save in the DCF file.
17. Resolved the issue that AES code only 32numbers when open a codeplug.
18. Fixed an issue in which APRS import/export does not work well.
19. When the repeater function is ON, the radio will auto disable Optional Setting - Volume/Audio - Maximum Volume, to resolve the low audio issue in repeater mode.
20. Resolved the issue that Menu and Exit key on microphone is invalid when repeater function is ON.
21. Resolved the issue that certain callers will not decode and show up as being received on the D578UV radio

Firmware	CPS	Icon	SCT 3258	BT Version	APRS Version	BT01 Firmware
V1.03	V1.03	-	2.01.07BA	10033	-	-

Firmware V1.0a | 2019-4-30

Changes

1. Add functions Zone+, Zone-, Menu Exit to the PA-PD programmed keys in CPS
2. Correct the microphone UP/DOWN key function
3. Resolved the issue that Radio Voltage indicator shows wrong value:1.37 Volts instead of 13.7 Volts
4. Resolved the issue that Chinese language is there when set up GPS antenna
5. Allow the PUSH key to switch date/time set after Reset.
6. Add the “Export Data Conversion File” function in CPS.
7. Allow the D578 CPS open D868/D878 codeplug directly
8. Add “Exclude channel from roaming” function in CPS.
9. Resolved the issue that CTCSS tone cannot be edited in CPS.

Firmware	CPS	Icon	SCT 3258	BT Version	APRS Version	BT01 Firmware
V1.0a	-	-	-	-	-	-